

**BOCES Pathways at Remington Lead Testing Results**

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking (Y/N/Potentially)	Notes	Remediation
CVBF3	161024004-055	< 0.001	10/28/2016 20:46					
CVFD9A	161024004-054	0.003	10/28/2016 20:41					
CVFS9B	161024004-053	< 0.001	10/28/2016 20:35					
CVR1101	161024004-094	0.009	10/31/2016 16:42	1101 Restroom	Sink	P		
CVR1101C	161024004-093	0.022	10/31/2016 16:37	1101 C	Sink	Y		
CVR1105A	161024004-071	0.003	10/28/2016 23:52	1105 Hallway	Left Girls Sink	P		
CVR1105B	161024004-072	0.002	10/28/2016 23:58	1105 Hallway	Center Girls Sink	P		
CVR1105C	161024004-073	0.002	10/29/2016 0:03	1105 Hallway	Right Girls Sink	P		
CVR1105D	161024004-074	0.007	10/29/2016 0:20	1105 Hallway	Left Boys Sink	P		
CVR1105E	161024004-075	0.009	10/29/2016 0:37	1105 Hallway	Center Boys Sink	P		
CVR1105G	161024004-096	0.004	10/31/2016 17:05	1105 Nurse	Bathroom Sink	Y		
CVR1105H	161024004-069	0.004	10/28/2016 23:41	1105 Nurse	Sink	Y		
CVR1201A	161024004-012	0.004	10/28/2016 11:33	1201	Sink	P		
CVR1201B	161024004-013	0.037	10/28/2016 11:47	1201	Bathroom Sink	P		
CVR1203A	161024004-014	0.01	10/28/2016 12:04	1203	Sink	P		
CVR1203B	161024004-083	0.05	10/29/2016 2:08	1203	Bathroom Sink	P		
CVR1203B	161024004-083	0.045	10/29/2016 1:59	1203	Bathroom Sink	P	Duplicate	
CVR1205A	161024004-084	0.192	10/31/2016 14:38	1205	Sink	P		

**BOCES Pathways at Remington Lead Testing Results**

CVR1205B	161024004-085	<b>0.057</b>	10/31/2016 15:03	1205	Bathroom Sink	P		
CVR1208A	161024004-002	<b>0.017</b>	10/27/2016 21:34	1208 Kitchen	Sink	Y		
CVR1208B	161024004-003	<b>0.046</b>	10/27/2016 21:48	1208 Kitchen	Sink	Y		
CVR1208B	161024004-003	<b>0.043</b>	10/27/2016 21:40	1208 Kitchen	Sink	Y	Duplicate	
CVR1208C	161024004-004	<b>0.039</b>	10/27/2016 22:02	1208 Kitchen	Sink	Y		
CVR1208D	161024004-005	<b>0.031</b>	10/27/2016 22:07	1208 Kitchen	Kettle	Y		
CVR1208E	161024004-006	<b>0.009</b>	10/27/2016 22:13	1208 Kitchen	Kettle	Y		
CVR1208S	161024004-007	<b>0.091</b>	10/28/2016 10:20	1208 Restroom	Sink	P		
CVR1209S	161024004-089	<b>0.047</b>	10/31/2016 16:14	1209	Slop Sink	P		
CVR1211	161024004-092	<b>0.001</b>	10/31/2016 16:31	1211 Faculty	Sink	Y		
CVR1211A	161024004-090	<b>0.007</b>	10/31/2016 16:20	1211 A Restroom	Women's Sink	P		
CVR1211B	161024004-091	<b>&lt; 0.001</b>	10/31/2016 16:25	1211 A Restroom	Men's Sink	P		
CVR1212S	161024004-001	<b>0.251</b>	10/28/2016 10:14	1212	Slop Sink	P		
CVR1215BF	161024004-010	<b>0.015</b>	10/28/2016 10:25	1215 Boys Locker Rm	Fountain	Y		
CVR1215BS	161024004-011	<b>0.065</b>	10/28/2016 10:39	1215 Boys Locker Rm	Sink	Y		
CVR1215F	161024004-008	<b>0.209</b>	10/28/2016 10:03	1215 Girls Locker Rm	Fountain	Y		
CVR1215S	161024004-009	<b>0.216</b>	10/28/2016 10:08	1215 Girls Locker Rm	Sink	Y		
CVR1303A	161024004-044	<b>&lt; 0.001</b>	10/28/2016 19:36	1303	Sink	P		
CVR1303B	161024004-045	<b>0.002</b>	10/28/2016 19:41	1303	Bathroom Sink	P		
CVR1303C	161024004-111	<b>0.046</b>	10/31/2016 19:35	1303	Mop Filler	N		

**BOCES Pathways at Remington Lead Testing Results**

CVR1303F	161024004-046	< 0.001	10/28/2016 19:47	1303	Fountain	Y		
CVR1305	161024004-047	0.002	10/28/2016 19:52	1305	Bathroom Sink	P		
CVR1305A	161024004-048	0.01	10/28/2016 20:09	1305	Mop Filler	N		
CVR1307A	161024004-049	0.002	10/28/2016 20:14	1307	Sink	P		
CVR1307B	161024004-051	0.002	10/28/2016 20:25	1307	Bathroom Sink	P		
CVR1307C	161024004-052	0.015	10/28/2016 20:30	1307	Mop Filler	N		
CVR1307F	161024004-050	< 0.001	10/28/2016 20:19	1307	Fountain	Y		
CVR1402	161024004-076	0.082	10/29/2016 1:00	1402	Bathroom Sink	P		
CVR1404A	161024004-078	0.005	10/29/2016 1:31	1404	Sink	P		
CVR1404B	161024004-079	0.032	10/29/2016 1:36	1404	Bathroom Sink	P		
CVR1405	161024004-077	0.049	10/29/2016 1:14	1405	Sink	P		
CVR1406A	161024004-080	0.005	10/29/2016 1:42	1406	Sink	P		
CVR1406B	161024004-081	0.012	10/29/2016 1:48	1406	Bathroom Sink	P		
CVR1407A	161024004-060	0.029	10/28/2016 21:42	1407	Sink	P		
CVR1407B	161024004-061	0.213	10/28/2016 22:12	1407	Bathroom Sink	P		
CVR1407B	161024004-061	0.195	10/28/2016 22:04	1407	Bathroom Sink	P	Duplicate	
CVR1408A	161024004-056	0.061	10/28/2016 21:11	1408	Sink	P		
CVR1408A	161024004-056	0.054	10/28/2016 21:03	1408	Sink	P	Duplicate	
CVR1408B	161024004-057	0.047	10/28/2016 21:25	1408	Sink	P		
CVR1409A	161024004-064	< 0.001	10/28/2016 23:02	1409	Sink	P		

**BOCES Pathways at Remington Lead Testing Results**

CVR1409B	161024004-065	<b>0.007</b>	10/28/2016 23:07	1409	Bathroom Sink	P		
CVR1410A	161024004-058	<b>0.009</b>	10/28/2016 21:31	1410	Sink	P		
CVR1410B	161024004-059	<b>0.02</b>	10/28/2016 21:36	1410	Bathroom Sink	P		
CVR1411A	161024004-029	<b>0.001</b>	10/28/2016 14:25	1411	Sink	P		
CVR1411B	161024004-030	<b>0.051</b>	10/28/2016 14:39	1411	Bathroom Sink	P		
CVR1412A	161024004-062	<b>0.002</b>	10/28/2016 22:29	1412	Sink	P		
CVR1412B	161024004-063	<b>0.006</b>	10/28/2016 22:45	1412	Bathroom Sink	P		
CVR1413	161024004-031	<b>0.001</b>	10/28/2016 17:06	1413	Sink	Y		
CVR1413	161024004-031	<b>0.001</b>	10/28/2016 15:01	1413	Sink	Y		
CVR1414A	161024004-067	<b>0.011</b>	10/28/2016 23:29	1414	Sink	Y		
CVR1414B	161024004-068	<b>0.02</b>	10/28/2016 23:35	1414	Bathroom Sink	Y		
CVR2401	161024004-104	<b>0.015</b>	10/31/2016 18:39	2401	Sink	Y		
CVR2402A	161024004-107	<b>0.029</b>	10/31/2016 19:12	2402	Sink	P		
CVR2402B	161024004-108	<b>0.01</b>	10/31/2016 19:18	2402	Sink	P		
CVR2403	161024004-103	<b>0.009</b>	10/31/2016 18:22	2403	Sink	Y		
CVR2404A	161024004-105	<b>0.007</b>	10/31/2016 18:45	2404	Sink	P		
CVR2404B	161024004-106	<b>0.014</b>	10/31/2016 19:07	2404	Sink	P		
CVR2407	161024004-097	<b>0.013</b>	10/31/2016 17:11	2407	Sink	P		
CVR2409	161024004-024	<b>0.008</b>	10/28/2016 13:57	2409	Sink	Y		
CVR2410S	161024004-098	<b>0.037</b>	10/31/2016 17:25	2410	Slop Sink	P		

**BOCES Pathways at Remington Lead Testing Results**

CVR2411	161024004-022	<b>0.005</b>	10/28/2016 13:34	2411	Sink	Y		
CVR2413	161024004-021	<b>0.011</b>	10/28/2016 13:16	2413	Sink	Y		
CVR2414	161024004-025	<b>0.017</b>	10/28/2016 14:03	2414	Sink	Y		
CVR2415	161024004-018	<b>0.013</b>	10/28/2016 12:37	2415	Sink	Y		
CVR2416	161024004-023	<b>0.01</b>	10/28/2016 13:40	2416	Sink	Y		
CVR2417	161024004-015	<b>0.002</b>	10/28/2016 12:20	2417	Sink	Y		
CVR2418	161024004-020	<b>0.015</b>	10/28/2016 13:00	2418	Sink	Y		
CVR2420	161024004-019	<b>0.009</b>	10/28/2016 12:43	2420	Sink	Y		
CVR2421S	161024004-036	<b>0.056</b>	10/28/2016 15:54	2421	Slop Sink	P		
CVR2421S	161024004-036	<b>0.05</b>	10/28/2016 17:58	2421	Slop Sink	P	Duplicate	
CVR2422	161024004-017	<b>0.025</b>	10/28/2016 12:32	2422	Sink	Y		
CVR2424	161024004-042	<b>0.013</b>	10/28/2016 18:54	2424	Sink	Y		
CVR2425	161024004-032	<b>0.003</b>	10/28/2016 17:12	1425	Sink	P		
CVR2425	161024004-032	<b>0.003</b>	10/28/2016 15:06	1425	Sink	P		
CVR2426	161024004-041	<b>0.001</b>	10/28/2016 18:37	2426	Sink	Y		
CVRF1	161024004-112	<b>0.011</b>	11/7/2016 10:13	Facility Room Hall	Fountain	Y		
CVRF1A	161024004-095	<b>0.004</b>	10/31/2016 16:48	Across from Cafe	Fountain	Y		
CVRF2	161024004-070	<b>&lt; 0.001</b>	10/28/2016 23:47	1211 Hallway	Fountain	Y		
CVRF3	161024004-082	<b>0.003</b>	10/29/2016 1:54	1408 Hallway	Fountain	Y		
CVRF4	161024004-066	<b>&lt; 0.001</b>	10/28/2016 23:24	1409 Hallway	Fountain	Y		

**BOCES Pathways at Remington Lead Testing Results**

CVRF5	161024004-040	< 0.001	10/28/2016 18:32	2425 Hallway	Fountain	Y		
CVRF6	161024004-016	0.012	10/28/2016 12:26	2422 Hallway	Fountain	Y		
CVRF7	161024004-102	0.009	10/31/2016 18:16	2403	Fountain	Y		
CVRS1	161024004-086	0.422	10/31/2016 15:26	Across From 1205	Sink	P		
CVRS2	161024004-087	0.371	10/31/2016 15:48	Across From 1205	Bathroom Sink	P		
CVRS3A	161024004-033	0.007	10/28/2016 15:12	2425 Hallway	Left Boys Restroom Sink	P		
CVRS3A	161024004-033	0.006	10/28/2016 17:17	2425 Hallway	Left Boys Restroom Sink	P		
CVRS3B	161024004-034	0.115	10/28/2016 15:34	2425 Hallway	Center Boys Restroom Sink	P		
CVRS3B	161024004-034	0.1	10/28/2016 17:39	2425 Hallway	Center Boys Restroom Sink	P	Duplicate	
CVRS3C	161024004-035	0.01	10/28/2016 15:40	2425 Hallway	Right Boys Restroom Sink	P		
CVRS3C	161024004-035	0.008	10/28/2016 17:45	2425 Hallway	Right Boys Restroom Sink	P		
CVRS4A	161024004-037	0.021	10/28/2016 18:15	2425 Hallway	Left Girls Restroom Sink	P		
CVRS4B	161024004-038	0.004	10/28/2016 18:21	2425 Hallway	Center Girls Restroom Sink	P		
CVRS4C	161024004-039	0.002	10/28/2016 18:26	2425 Hallway	Right Girls Restroom Sink	P		
CVRS6A	161024004-026	0.012	10/28/2016 14:08	2414 Hallway	Left Girls Restroom Sink			
CVRS6B	161024004-027	0.009	10/28/2016 14:14	2414 Hallway	Center Girls Restroom Sink			
CVRS6C	161024004-028	0.019	10/28/2016 14:19	2414 Hallway	Right Girls Restroom Sink			
CVRS7A	161024004-099	0.016	10/31/2016 17:31	2414 Hallway	Left Boys Restroom Sink	P		
CVRS7B	161024004-100	0.01	10/31/2016 17:37	2414 Hallway	Center Boys Restroom Sink	P		
CVRS7C	161024004-101	0.142	10/31/2016 18:10	2414 Hallway	Right Boys Restroom Sink	P		

### BOCES Pathways at Remington Lead Testing Results

CVRS8A	161024004-109	<b>0.005</b>	10/31/2016 19:24	Outside Bathroom	Sink	P		
CVRS8B	161024004-110	<b>0.004</b>	10/31/2016 19:30	Outside Bathroom	Sink	P		
CVRS9	161024004-043	<b>0.013</b>	10/28/2016 19:30	Outside Concession	Sink	Y		

44

4