

**Barringer Road Elementary School Lead Testing Results**

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking (Y/N/Potentially)	Notes	Remediation
CVB1426SA	161007049-001	< 0.001	10/14/2016 0:18	1426	Sink	P		
CVB1426SB	161007049-002	0.005	10/14/2016 0:23	1426	Bathroom	P	OLD LOCKER RM Discon.	
CVB1413	161007049-003	< 0.001	10/14/2016 0:29	1413 Hallway	Fountain	Y	OLD LOCKER RM	
CVB1403SA	161007049-004	< 0.001	10/14/2016 0:45	1403	Sink	Y		
CVB1403SB	161007049-005	0.002	10/14/2016 0:51	1403	Sink	Y		
CVB1401SA	161007049-006	< 0.001	10/14/2016 0:56	1401	Sink	Y		
CVB1401SB	161007049-007	< 0.001	10/14/2016 1:01	1401	Sink	Y		
CVB1401SC	161007049-008	0.003	10/14/2016 1:07	1401	Bathroom	P		
CVB1422SA	161007049-009	0.001	10/14/2016 1:12	1422	Sink	Y		
CVB1422SB	161007049-010	0.002	10/14/2016 1:17	1422	Sink	Y		
CVB1424S	161007049-011	0.002	10/14/2016 1:45	1424	Slop Sink	Y		
CVB1413SA	161007049-012	< 0.001	10/14/2016 1:50	1413	Sink	Y		
CVB1413SB	161007049-013	< 0.001	10/14/2016 1:55	1413	Sink	Y		
CVB1415SA	161007049-014	0.001	10/14/2016 2:01	1415	Sink	Y		
CVB1415SB	161007049-015	< 0.001	10/14/2016 21:09	1415	Sink	Y		
CVB1409SA	161007049-016	< 0.001	10/14/2016 21:25	1409	Sink	Y		
CVB1409SB	161007049-017	0.002	10/14/2016 21:31	1409	Sink	Y		
CVBF	161007049-018	0.003	10/14/2016 21:36	By 1409	Drinking Fountain	Y		
CVB1407SA	161007049-019	< 0.001	10/14/2016 21:41	1407	Sink	Y		
CVB1407SB	161007049-020	< 0.001	10/14/2016 21:47	1407	Sink	Y		
CVB1405SA	161007049-021	< 0.001	10/14/2016 22:03	1405	Sink	Y		
CVB1405SB	161007049-022	0.002	10/14/2016 22:08	1405	Sink	Y		
CVB1406SB	161007049-023	0.002	10/14/2016 22:14	1406	Sink	Y		
CVB1408SA	161007049-024	< 0.001	10/14/2016 22:19	1408	Sink	Y		
CVB1408SB	161007049-025	0.002	10/14/2016 22:25	1408	Sink	Y		
CVB1410SA	161007049-026	< 0.001	10/14/2016 22:41	1410	Sink	Y		
CVB1410SB	161007049-027	< 0.001	10/15/2016 0:47	1410	Sink	Y		
CVB1412SA	161007049-028	0.001	10/15/2016 0:53	1412	Sink	Y		

**Barringer Road Elementary School Lead Testing Results**

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking (Y/N/Potentially)	Notes	Remediation
CVB1412SB	161007049-029	0.003	10/15/2016 0:58	1412	Sink	Y		
CVB1414SA	161007049-030	0.002	10/15/2016 1:03	1414	Sink	Y		
CVB1414SB	161007049-031	0.003	10/14/2016 11:18	1414	Sink	Y		
CVB1416SA	161007049-032	< 0.001	10/14/2016 11:34	1416	Sink	Y		
CVB1416SB	161007049-033	0.006	10/14/2016 11:56	1416	Sink	Y		
CVBS10	161007049-034	0.003	10/14/2016 12:01	1416 Hallway	Women's Sink	P		
CVB1420SA	161007049-035	< 0.001	10/14/2016 12:07	1420	Sink	Y		
CVB1420SB	161007049-036	0.007	10/14/2016 12:12	1420	Sink	Y		
CVB1323S	161007049-037	0.001	10/14/2016 12:18	1323	Sink	Y		
CVB1323F	161007049-038	< 0.001	10/14/2016 12:23	1323	Fountain	Y		
CVB1325S	161007049-039	< 0.001	10/14/2016 12:28	1325	Sink	Y		
CVB1325F	161007049-040	< 0.001	10/14/2016 12:45	1325	Fountain	Y		
CVBS9A	161007049-041	< 0.001	10/14/2016 12:50	1325 Hallway	Men's Bathroom	P		
CVBS9C	161007049-042	< 0.001	10/14/2016 13:07	1325 Hallway	Women's Bathroom	P		
CVB1316S	161007049-043	< 0.001	10/14/2016 13:17	1316	Sink	Y		
CVB1314S	161007049-044	< 0.001	10/14/2016 13:23	1314	Sink	Y		
CVB1312S	161007049-045	0.001	10/14/2016 13:39	1312	Sink	Y		
CVB1310S	161007049-046	< 0.001	10/14/2016 13:45	1310	Sink	Y		
CVB1105S	161007049-047	0.003	10/14/2016 13:50	1105	Sink	N	Old Locker Room	
CVB1402S	161007049-048	< 0.001	10/14/2016 13:56	1402	Sink	Y		
CVBF5	161007049-049	< 0.001	10/14/2016 14:02	1402 Hallway	Fountain	Y		
CVB1406SA	161007049-050	< 0.001	10/14/2016 14:19	1406	Sink	Y		
CVB1203S	161007049-051	< 0.001	10/14/2016 14:47	1203	Sink	Y		
CVBS1	161007049-052	< 0.001	10/14/2016 14:53	Women by 1203	Sink	P		
CVBS2	161007049-053	< 0.001	10/14/2016 14:59	Men by 1203	Sink	P		
CVB1205S	161007049-054	0.001	10/14/2016 15:05	1205	Sink	P		
CVBF1	161007049-055	0.002	10/14/2016 15:10	Hallway by 1205	Drinking Fountain	Y		
CVB1207S	161007049-056	0.002	10/14/2016 15:16	1207	Sink	Y		

**Barringer Road Elementary School Lead Testing Results**

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking (Y/N/Potentially)	Notes	Remediation
CVB1209S	161007049-057	< 0.001	10/14/2016 15:44	1209	Sink	Y		
CVB1211S	161007049-058	< 0.001	10/14/2016 15:50	1211	Sink	Y		
CVB1213S	161007049-059	< 0.001	10/14/2016 15:55	1213	Sink	Y		
CVB1218S	161007049-060	< 0.001	10/14/2016 16:01	1218	Sink	Y		
CVB1216S	161007049-061	< 0.001	10/14/2016 16:29	1216	Sink	Y		
CVB1214S	161007049-062	< 0.001	10/14/2016 16:35	1214	Sink	Y		
CVB1212S	161007049-063	< 0.001	10/14/2016 16:40	1212	Sink	Y		
CVBS3A	161007049-064	< 0.001	10/14/2016 16:46	1208	Boys Bathroom	P		
CVBS3B	161007049-065	< 0.001	10/14/2016 16:52	1208	Boys Bathroom	P		
CVBS3C	161007049-066	< 0.001	10/14/2016 16:58	1208	Boys Bathroom	P		
CVBS3D	161007049-067	< 0.001	10/14/2016 17:04	1208	Boys Bathroom	P		
CVBS3E	161007049-068	< 0.001	10/14/2016 17:09	1208	Girls Bathroom	P		
CVBS3F	161007049-069	0.001	10/14/2016 17:26	1208	Girls Bathroom	P		
CVBS3G	161007049-070	< 0.001	10/14/2016 17:32	1208	Girls Bathroom	P		
CVBS3H	161007049-071	< 0.001	10/14/2016 17:49	1208	Girls Bathroom	P		
CVBS3I	161007049-072	< 0.001	10/14/2016 18:23	1208	Utility Sink	P		
CVB1204AS	161007049-073	0.003	10/14/2016 18:28	1204 A	Sink	P		
CVBF2	161007049-074	< 0.001	10/14/2016 18:34	1302 Hallway	Drinking Fountain	Y		
CVBS4A	161007049-075	0.002	10/14/2016 18:40	Kitchen	Sink	Y		
CVBS4B	161007049-076	0.002	10/14/2016 18:45	Kitchen	Sink	Y		
CVBS4C	161007049-077	< 0.001	10/14/2016 18:51	Kitchen	Sink	Y		
CVBS4D	161007049-078	0.019	10/14/2016 18:57	Kitchen	Sink	Y	Handles Removed	Replace & Retest
CVBS8C	161007049-079	0.001	10/14/2016 19:02	1302Boys Bathroom	Left Sink	P		
CVBS8D	161007049-080	< 0.001	10/14/2016 19:19	1302Girls Bathroom	High Sink	P		
CVBS8E	161007049-081	< 0.001	10/14/2016 19:24	1302 Girls Bathroom	Mid Sink	P		
CVBS8F	161007049-082	< 0.001	10/14/2016 19:40	1302 Girls Bathroom	Right Sink	P		
CVB1307S	161007049-083	< 0.001	10/14/2016 19:46	1307	Slop Sink	P		
CVB1311S	161007049-084	0.001	10/14/2016 19:52	1311	Sink	Y		

**Barringer Road Elementary School Lead Testing Results**

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking (Y/N/Potentially)	Notes	Remediation
CVB1313S	161007049-085	< 0.001	10/14/2016 19:57	1313	Sink	Y		
CVBF4	161007049-086	< 0.001	10/14/2016 20:14	1313 Hallway	Drinking Fountain	Y		
CVB1315S	161007049-087	< 0.001	10/14/2016 20:20	1315	Sink	Y		
CVB1317S	161007049-088	< 0.001	10/14/2016 20:25	1317	Sink	Y		
CVB1319S	161007049-089	< 0.001	10/14/2016 20:31	1319	Sink	Y		
CVB1319F	161007049-090	< 0.001	10/14/2016 20:36	1319	Fountain	Y		
CVB1321S	161007049-091	< 0.001	10/14/2016 20:42	1321	Sink	Y		
CVB1321F	161007049-092	< 0.001	10/15/2016 1:59	1321	Fountain	Y		
CVBS4E	161007049-093	0.002	10/15/2016 2:16	Kitchen	Sink	Y		
CVBS4F	161007049-094	< 0.001	10/15/2016 2:22	Kitchen	Sink	Y		
CVBK1	161007049-095	0.001	10/15/2016 4:36	Kitchen	Left Kettle	Y		
CVBK2	161007049-096	< 0.001	10/15/2016 4:42	Kitchen	Right Kettle	Y		
CVBS5	161007049-097	< 0.001	10/15/2016 4:47	Kitchen Bathroom	Sink	P		
CVB1101S	161007049-098	< 0.001	10/15/2016 4:52	1101	Slop Sink	P		
CVBS6	161007049-099	< 0.001	10/15/2016 4:58	Main Office	Sink	Y		
CVBS7A	161007049-100	< 0.001	10/15/2016 5:04	Nurses	Sink	Y		
CVBS7B	161007049-101	< 0.001	10/15/2016 5:10	Nurses Bathroom	Sink	P		
CVB1302S	161007049-102	0.002	10/15/2016 5:15	1302	Sink	P		
CVB1302SA	161007049-103	< 0.001	10/15/2016 5:32	Rm 113 Women's Bathroom	Sink	P		
CVB1302SB	161007049-104	< 0.001	10/15/2016 5:38	Rm 112 Men's Bathroom	Sink	P		
CVBS8A	161007049-105	< 0.001	10/15/2016 5:43	1302 Boys Bathroom	High Sink	P		
CVBS8B	161007049-106	< 0.001	10/15/2016 5:49	1302 Boys Bathroom	Mid Sink	P		
CVB1105F				1105	Fountain	N	Old Locker R. Discon.	
CVBSF2				Cafeteria	Drinking Fountain	Y		