

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA0510	161107007-124	< 0.001	11/17/2016 14:58	510	Sink	Y		
CVA0512	161107007-123	< 0.001	11/17/2016 14:52	512	Sink	P		
CVA0512A	161107007-121	< 0.001	11/17/2016 14:30	0512 Men	Sink	P		
CVA0512B	161107007-122	< 0.001	11/17/2016 14:47	0512 Women	Sink	P		
CVA0518S	161107007-120	0.001	11/17/2016 14:25	518	Slop Sink	P		
CVA0526	161107007-116	< 0.001	11/17/2016 13:11	526	Sink	P		
CVA0526A	161107007-117	< 0.001	11/17/2016 13:50	0526 Men	Sink	P		
CVA0526B	161107007-118	< 0.001	11/17/2016 14:08	0526 Women	Sink	P		
CVA0526C	161107007-119	< 0.001	11/17/2016 14:19	0526 Handicap	Sink	P		
CVA0530S	161107007-113	< 0.001	11/17/2016 12:32	530	Slop Sink	P		
CVA1035C	161107007-105	< 0.001	11/17/2016 11:15	1305 Kitchen	Prep Table Sink	P		
CVA1035D	161107007-106	< 0.001	11/17/2016 11:20	1305 Kitchen	Left Kettle	P		
CVA1035E	161107007-107	< 0.001	11/17/2016 11:25	1305 Kitchen	Right Kettle	P		
CVA1051E	161107009-009	0.073	11/17/2016 15:42	1501	Sink	P	Handles Removed	
CVA1101S	161107007-094	< 0.001	11/16/2016 18:54	1101	Slop Sink	P		
CVA1103	161107007-093	< 0.001	11/16/2016 18:49	1103B	Sink	Y		
CVA1103A	161107007-091	< 0.001	11/16/2016 18:38	1103 G Men	Sink	P		
CVA1103B	161107007-092	< 0.001	11/16/2016 18:44	1103 G Ladies	Sink	P		
CVA1109A	161107007-095	< 0.001	11/16/2016 19:00	1109 Ladies	Sink	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA1109A	161107007-095	< 0.001	11/17/2016 9:59:52SM	1109 Ladies	Sink	P		
CVA1109B	161107007-096	< 0.001	11/17/2016 10:05:13AM	1109 Ladies	Sink	P		
CVA1109C	161107007-097	< 0.001	11/17/2016 10:21	1109 Ladies	Sink	P		
CVA1109D	161107007-098	< 0.001	11/17/2016 10:26	1109 Men's	Left Sink			
CVA1109E	161107007-043	< 0.001	11/16/2016 11:09:53AM	1109 Men's	Center Sink			
CVA1109F	161107007-044	< 0.001	11/16/2016 11:15:33AM	1109 Men's	Right Sink			
CVA1112	161107007-050	0.014	11/16/2016 12:12	1112 Locker Rm	Sink	P		
CVA1112A	161107007-051	0.001	11/16/2016 12:23	1112 Locker Rm	Sink	P		
CVA1112B	161107007-052	0.004	11/16/2016 12:29	1112Coaches Locker Rm	Sink	P		
CVA1117A1	161107007-056	0.009	11/16/2016 13:30	1117 A	Sink	P		
CVA1117A	161107007-053	0.004	11/16/2016 12:35	1117 Women's Locker	Left Sink	P		
CVA1117B	161107007-054	< 0.001	11/16/2016 13:08	1117 Women's Locker	Center Sink	P		
CVA1117C	161107007-055	< 0.001	11/16/2016 13:25	1117 Women's Locker	Right Sink	P		
				1119 Men's Locker	Sink	P		DOESN'T WORK
CVA1119A1	161107007-031	0.002	11/10/2016 18:44	1119 A	Sink	P		
CVA1119B	161107009-045	< 0.001	11/22/2016 19:11	1119 Men's Locker	Sink	P		
CVA1119C	161107009-046	< 0.001	11/22/2016 19:17	1119 Men's Locker	Sink	P		
CVA1119C1	161107009-047	0.002	11/22/2016 19:23	1119 C	Sink	P		
CVA1203A	161107007-089	< 0.001	11/16/2016 18:16	1203	Sink Nurse	Y		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA1203B	161107007-090	< 0.001	11/16/2016 18:22	1203	Sink Nurse	Y		
CVA1205F	161107007-088	< 0.001	11/16/2016 18:11	1205 Hallway	Drinking Fountain	Y		
CVA1205S	161107007-087	< 0.001	11/16/2016 18:05	1205	Slop Sink	P		
CVA1208A	161107007-074	< 0.001	11/16/2016 15:58	1208	Sink	Y		
CVA1208B	161107007-075	< 0.001	11/16/2016 16:20	1208	Sink	Y		
CVA1208C	161107007-076	< 0.001	11/16/2016 16:48	1208	Sink	Y		
CVA1208D	161107007-077	< 0.001	11/16/2016 16:54	1208	Sink	Y		
CVA1210A	161107007-070	0.002	11/16/2016 15:13	1210	Sink	Y		
CVA1210B	161107007-071	0.001	11/16/2016 15:30	1210	Sink	Y		
CVA1210C	161107007-072	< 0.001	11/16/2016 15:47	1210	Sink	Y		
CVA1210D	161107007-073	< 0.001	11/16/2016 15:53	1210	Sink	Y		
CVA1211A	161107007-078	< 0.001	11/16/2016 16:59	1211	Sink Art	P		
CVA1211B	161107007-079	< 0.001	11/16/2016 17:04	1211	Sink Art	P		
CVA1211C	161107007-080	< 0.001	11/16/2016 17:10	1211	Sink Art	P		
CVA1211D	161107007-081	0.005	11/16/2016 17:16	1211	Sink Art	P		
CVA1211E	161107007-082	< 0.001	11/16/2016 17:21	1211	Sink Art	P		
CVA1211F	161107007-083	< 0.001	11/16/2016 17:43	1211	Sink Art	P		
CVA1211G	161107007-084	0.001	11/16/2016 17:49	1211	Sink	P		
CVA1213A	161107007-085	< 0.001	11/16/2016 17:54	1213	Sink Art	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA1213B	161107007-086	0.002	11/16/2016 18:00	1213	Sink Art	P		
CVA1216A	161107007-064	0.001	11/16/2016 14:28	1216	Boys Left Sink	P		
CVA1216B	161107007-065	< 0.001	11/16/2016 14:34	1216	Boys Right Sink	P		
CVA1216C	161107007-066	< 0.001	11/16/2016 14:50	1216	Girls Left Sink	P		
CVA1216D	161107007-067	0.002	11/16/2016 14:56	1216	Girls Right Sink	P		
CVA1216S	161107007-063	0.003	11/16/2016 14:22	1216	Slop Sink	P		
CVA1302A	161107007-061	0.002	11/16/2016 14:11	1302 Men	Sink	P		
CVA1302B	161107007-062	0.001	11/16/2016 14:17	1302 Ladies	Sink	P		
CVA1302K	161107007-060	< 0.001	11/16/2016 14:05	1302 K	Kitchen Sink	Y		
CVA1302S	161107007-059	0.002	11/16/2016 13:59	1302 Super	Bathroom Sink	P		
CVA1305A	161107007-103	< 0.001	11/17/2016 11:04	1305 Kitchen	Dish Washing Sink by Door	P		
CVA1305B	161107007-104	< 0.001	11/17/2016 11:09	1305 Kitchen	Dish Washing Sink	P		
CVA1305CB	161107007-112	0.001	11/17/2016 12:27	1305 C Bathroom	Sink	P		
CVA1305F	161107007-108	0.001	11/17/2016 11:31	1305 Kitchen	Back Prep Table	P		
CVA1305G	161107007-109	< 0.001	11/17/2016 11:58	1305 Kitchen	Back Left Sink	P		
CVA1305H	161107007-110	< 0.001	11/17/2016 12:04	1305 Kitchen	Right Back Sink	P		
CVA1305I	161107007-111	< 0.001	11/17/2016 12:21	1305 Kitchen	Hand Washing Sink	P		
CVA1306	161107007-032	< 0.001	11/10/2016 18:50	1306 Men's Locker	Sink	P		
CVA1306A	161107007-033	0.001	11/16/2016 9:40	1306 Women's Locker	Left Sink	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA1306B	161107007-034	0.001	11/16/2016 10:07	1306 Women's Locker	Right Sink	P		
CVA1311	161107007-102	< 0.001	11/17/2016 10:58	1311	Sink	P		
CVA1313S	161107007-101	< 0.001	11/17/2016 10:53:34AM	1313	Slop Sink	P		
CVA1317	161107007-099	< 0.001	11/17/2016 10:31	1317	Sink	Y		
CVA1317S	161107007-100	< 0.001	11/17/2016 10:37	1317	Slop Sink	P		
CVA1321FA	161107007-035	< 0.001	11/16/2016 10:13	1321	High Drinking Fountain	Y		
CVA1321FB	161107007-036	< 0.001	11/16/2016 10:18	1321	Low Drinking Fountain	Y		
CVA1321SA	161107007-037	0.007	11/16/2016 10:23	1321	Left Sink	P		
CVA1321SB	161107007-038	0.005	11/16/2016 10:29	1321	Right Sink	P		
CVA1323FA	161107007-039	< 0.001	11/16/2016 10:35	1323	High Drinking Fountain	Y		
CVA1323FB	161107007-040	< 0.001	11/16/2016 10:41:34AM	1323	Low Drinking Fountain	Y		
CVA1323SA	161107007-041	0.017	11/16/2016 10:47:31AM	1323	Left Sink	P	Handles Removed	
CVA1323SB	161107007-042	0.002	11/16/2016 11:04:11AM	1323	Right Sink	P		
CVA1327FA	161107007-015	< 0.001	11/10/2016 16:23	1327	High Drinking Fountain	Y		
CVA1327FB	161107007-016	< 0.001	11/10/2016 16:29	1327	Low Drinking Fountain	Y		
CVA1327SA	161107007-017	< 0.001	11/10/2016 16:35	1327	Left Sink	P		
CVA1327SB	161107007-018	0.002	11/10/2016 16:41	1327	Right Sink	P		
CVA1327SC	161107007-019	< 0.001	11/10/2016 16:46	Dark Room	Sink	P		
CVA1329FA	161107007-020	< 0.001	11/10/2016 16:51	1329	High Drinking Fountain	Y		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA1329FB	161107007-021	< 0.001	11/10/2016 16:57	1329	Low Drinking Fountain	Y		
CVA1329SA	161107007-022	0.024	11/10/2016 17:14	1329	Left Sink	P	Handles Removed	
CVA1329SB	161107007-023	< 0.001	11/10/2016 17:19	1329	Right Sink	P		
CVA1400A	161107007-024	< 0.001	11/10/2016 17:25	1400	Women's Sink	P		
CVA1400B	161107007-025	< 0.001	11/10/2016 17:47	1400	Men's Sink	P		
CVA1410A	161107007-132	0.003	11/17/2016 16:00	1410	Sink	P		
CVA1410B	161107009-048	0.008	11/22/2016 19:56	1410	Sink	P		
CVA1410C	161107009-049	0.01	11/22/2016 20:13	1410	Sink	P		
CVA1413A	161107007-001	< 0.001	11/10/2016 13:56	1413 Hallway Men	Sink	P		
CVA1413AA	161107007-028	0.01	11/10/2016 18:16	1413A	Sink	P		
CVA1413B	161107007-002	< 0.001	11/10/2016 14:02	1413 Hallway Men	Sink	P		
CVA1413BB	161107007-027	0.002	11/10/2016 18:10	1413B	Sink	Y		
CVA1413C	161107007-003	< 0.001	11/10/2016 14:24	1413 Hallway Women	Sink	P		
CVA1413D	161107007-004	< 0.001	11/10/2016 14:30	1413 Hallway Women	Sink	P		
CVA1414S	161107007-131	0.006	11/17/2016 15:54	1414	Slop Sink	N		
CVA1416A	161107009-050	0.015	11/22/2016 20:18	1416	Sink	P		
CVA1416B	161107009-051	0.016	11/22/2016 20:24	1416	Sink	P	Handles Removed	
CVA1416C	161107009-052	0.016	11/22/2016 20:41	1416	Sink	P	Handles Removed	
CVA1419A	161107009-053	0.005	11/22/2016 20:47	1419 Hallway Men	Sink	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA1419B	161107009-054	0.001	11/22/2016 20:53	1419 Hallway Women	Sink	P		
CVA1423A	161107009-039	< 0.001	11/22/2016 18:16	1423A	Sink	Y		
CVA1425	161107009-056	0.017	11/22/2016 21:04	1425	Slop Sink	N	Handles Removed	
CVA1426AA	161107009-029	0.007	11/20/2016 0:44	1426 A	Sink	Y		
CVA1434	161107009-030	0.004	11/20/2016 0:49	1434	Sink	P		
CVA1436	161107009-031	0.168	11/22/2016 17:22	1436	Sink	P	Handles Removed	
CVA1440A	161107009-033	0.006	11/22/2016 17:33	1440 Hallway	Left Men Sink	P		
CVA1440B	161107009-034	0.004	11/22/2016 17:38	1440 Hallway	Right Men Sink	P		
CVA1440C	161107009-035	0.002	11/22/2016 17:55	1440 Hallway	Women Sink	P		
CVA1440D	161107009-036	0.006	11/22/2016 18:00	1440 Hallway	Women Sink	P		
CVA1440S	161107009-032	0.008	11/22/2016 17:28	1440	Slop Sink	P		
CVA1446	161107009-038	0.002	11/22/2016 18:11	1446	Sink	P		
CVA1501A	161107009-005	0.024	11/17/2016 14:56	1501	Sink	P	Handles Removed	
CVA1501A1	161107009-004	0.019	11/17/2016 14:20	1501	Prep Room Sink	P	Handles Removed	
CVA1501B	161107009-006	0.022	11/17/2016 15:01	1501	Sink	P	Handles Removed	
CVA1501C	161107009-007	0.041	11/17/2016 15:15	1501	Sink	P	Handles Removed	
CVA1501D	161107009-008	0.003	11/17/2016 15:20	1501	Sink	P		
CVA1501F	161107009-010	0.029	11/17/2016 15:59	1501	Sink	P	Handles Removed	
CVA1501G	161107009-011	0.118	11/17/2016 16:21	1501	Sink	P	Handles Removed	

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA1501H	161107009-012	0.123	11/17/2016 16:44	1501	Sink	P	Handles Removed	
CVA1501I	161107009-013	0.091	11/17/2016 17:06	1501	Sink	P	Handles Removed	
CVA1501J	161107009-014	0.062	11/17/2016 17:37	1501	Sink	P	Handles Removed	
CVA1501K	161107007-127	0.011	11/17/2016 15:15	1501	Sink	P		
CVA1501L	161107007-128	0.006	11/17/2016 15:20	1501	Sink	P		
CVA1501M	161107007-129	0.004	11/17/2016 15:26	1501	Sink	P		
CVA1501N	161107007-130	0.011	11/17/2016 15:48	1501	Sink	P		
CVA1502A	161107009-028	0.013	11/20/2016 0:38	1502	Sink	P		
CVA1502B	161107009-002	0.014	11/17/2016 14:09	1502	Sink	P		
CVA1502B1	161107009-001	0.091	11/17/2016 14:03	1502	Prep Room Sink	P	Handles Removed	
CVA1502C	161107009-003	0.003	11/17/2016 14:15	1502	Sink	p		
CVA1504A	161107009-022	0.022	11/19/2016 23:37	1504	Sink	P	Handles Removed	
CVA1504A1	161107009-027	0.002	11/20/2016 12:33:14AM	1504A	Sink	P		
CVA1504B	161107009-023	0.007	11/19/2016 23:43	1504	Sink	P		
CVA1504C	161107009-024	0.012	11/19/2016 23:48	1504	Sink	P		
CVA1504D	161107009-025	0.111	11/22/2016 17:17	1504	Sink	P	Handles Removed	
CVA1504E	161107009-026	0.004	11/20/2016 0:27	1504	Sink	P		
				1504	Sink	P	DOESN'T WORK	
CVA1506A	161107007-008	0.002	11/10/2016 15:04	1506	Sink	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA1506B	161107007-009	< 0.001	11/10/2016 15:38	1506	Sink	P		
CVA1506C	161107007-010	< 0.001	11/10/2016 15:44	1506	Sink	P		
CVA1506D	161107007-011	< 0.001	11/10/2016 15:49	1506	Sink	P		
CVA1506E	161107007-012	< 0.001	11/10/2016 15:55	1506	Sink	P		
CVA1506F	161107007-013	0.004	11/10/2016 16:01	1506	Sink	P		
CVA1506G	161107007-014	< 0.001	11/10/2016 16:18	1506	Sink	P		
CVA1506H	161107009-015	0.111	11/17/2016 18:00	1506	Sink	P	Handles Removed	
CVA1506I	161107009-016	0.003	11/17/2016 18:06	1506	Sink	P		
CVA1506J	161107009-017	0.006	11/17/2016 18:11	1506	Sink	P		
CVA1506K	161107009-018	< 0.001	11/17/2016 18:17	1506	Sink	P		
CVA1506L	161107009-019	0.002	11/17/2016 18:33	1506	Sink	P		
CVA1506M	161107009-020	0.004	11/17/2016 18:39	1506	Sink	P		
CVA1506N	161107009-021	0.002	11/19/2016 23:32	1506	Sink	P		
CVA1509S	161107007-005	< 0.001	11/10/2016 14:52	1509	Slop Sink	P		
CVA2105	161107007-068	0.002	11/16/2016 15:01	2105 Library	Outside Slop Sink	N		
CVA2413A	161107007-138	< 0.001	11/17/2016 17:01	2413 Men	Sink	P		
CVA2413B	161107007-139	< 0.001	11/17/2016 17:19	2413 Men	Sink	P		
CVA2413C	161107007-140	< 0.001	11/17/2016 17:24	2413 Women	Sink	P		
CVA2413D	161107009-057	< 0.001	11/22/2016 21:10	2413 Women	Sink	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA2429S	161107007-136	0.001	11/17/2016 16:22	2429	Slop Sink	P		
CVA2434A	161107009-040	0.002	11/22/2016 18:21	2434	Sink	P		
CVA2434B	161107009-041	0.001	11/22/2016 18:27	2434	Sink	P		
CVA2434C	161107009-042	< 0.001	11/22/2016 18:32	2434	Sink	P		
CVA2434D	161107007-029	< 0.001	11/10/2016 18:33	2434	Sink	P		
CVA2434S	161107007-030	0.003	11/10/2016 18:38	2434	Slop Sink	P		
CVA243A	161107007-134	0.001	11/17/2016 16:11	243 Teachers Lounge	Sink	P		
CVA243B	161107007-135	0.002	11/17/2016 16:16	243 Teachers Lounge	Sink	P		
CVA2504A	161107009-111	< 0.001	11/24/2016 1:59	2504	Sink	P		
CVA2504A1	161107009-097	0.011	11/23/2016 23:24	2504A	Sink	P		
CVA2504B	161107009-112	0.002	11/24/2016 2:16:41AM	2504	Sink	P		
CVA2504C	161107009-113	0.001	11/24/2016 2:22	2504	Sink	P		
CVA2504D	161107009-114	< 0.001	11/24/2016 2:27:53AM	2504	Sink	P		
CVA2504E	161107009-115	0.001	11/24/2016 2:33	2504	Sink	P		
CVA2504F	161107009-116	< 0.001	11/24/2016 2:39:03AM	2504	Sink	P		
CVA2504G	161107009-117	0.096	11/24/2016 2:53:04AM	2504	Sink	P	Handles Removed	
CVA2504H	161107009-118	0.017	11/24/2016 3:25	2504	Sink	P	Handles Removed	
CVA2504I	161107009-119	< 0.001	11/24/2016 3:41	2504	Sink	P		
CVA2504J	161107009-120	< 0.001	11/24/2016 3:47	2504	Sink	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA2504K	161107009-121	0.107	11/24/2016 4:01:51AM	2504	Sink	P	Handles Removed	
CVA2504L	161107009-122	0.004	11/24/2016 4:18	2504	Sink	P		
CVA2504M	161107009-123	0.008	11/24/2016 4:24:11AM	2504	Sink	P		
CVA2504N	161107009-124	0.027	11/24/2016 4:29	2504	Sink	P	Handles Removed	
CVA2505A	161107009-075	0.014	11/23/2016 19:11	2505	Sink	P		
CVA2505A1	161107009-080	0.064	11/23/2016 20:13	2505 A	Sink	P	Handles Removed	
CVA2505A2	161107009-081	< 0.001	11/23/2016 20:19	2505 Men	Sink	P		
CVA2505B	161107009-076	0.004	11/23/2016 19:17	2505	Sink	P		
CVA2505B2	161107009-082	< 0.001	11/23/2016 20:24	2505 Women	Sink	P		
CVA2505C	161107009-077	0.013	11/23/2016 19:22	2505	Sink	P		
CVA2505D	161107009-078	0.002	11/23/2016 19:27	2505	Sink	P		
CVA2505F	161107009-079	0.013	11/23/2016 20:00	2505	Sink	P		
CVA2505G	161107009-130	0.045	11/24/2016 5:39	2505	Sink	P	Handles Removed	
CVA2505J	161107009-129	0.191	11/24/2016 5:14	2505	Sink	P	Handles Removed	
CVA2505K	161107009-131	0.013	11/24/2016 5:44					
CVA2506A	161107009-098	0.012	11/23/2016 23:46	2506	Sink	P		
CVA2506A1	161107009-110	0.022	11/24/2016 1:54	2506 A	Sink	P	Handles Removed	
CVA2506B	161107009-099	0.003	11/24/2016 0:14	2506	Sink	P		
CVA2506C	161107009-100	0.003	11/24/2016 12:20:11AM	2506	Sink	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA2506D	161107009-101	0.205	11/24/2016 0:43	2506	Sink	P	Handles Removed	
CVA2506E	161107009-102	0.01	11/24/2016 12:49:13AM	2506	Sink	P		
CVA2506F	161107009-103	0.085	11/24/2016 1:03	2506	Sink	P	Handles Removed	
CVA2506G	161107009-104	0.001	11/24/2016 1:19	2506	Sink	P		
CVA2506I	161107009-105	0.003	11/24/2016 1:25	2506	Sink	P		
				2506	Sink	P		DOESN'T WORK
CVA2506J	161107009-106	0.002	11/24/2016 1:31	2506	Sink	P		
CVA2506K	161107009-107	0.006	11/24/2016 1:37:21AM	2506	Sink	P		
CVA2506L	161107009-108	0.001	11/24/2016 1:43:02SM	2506	Sink	P		
CVA2506M	161107009-109	< 0.001	11/24/2016 1:48	2506	Sink	P		
CVA2506N	161107009-132	0.002	11/24/2016 5:50:21AM					
CVA2508A	161107009-083	0.06	11/23/2016 20:38	2508	Sink	P	Handles Removed	
CVA2508B	161107009-084	0.282	11/23/2016 21:01	2508	Sink	P	Handles Removed	
CVA2508C	161107009-085	0.002	11/23/2016 21:19	2508	Sink	P		
CVA2508D	161107009-086	0.003	11/23/2016 21:24	2508	Sink	P		
CVA2508E	161107009-087	0.018	11/23/2016 21:30	2508	Sink	P	Handles Removed	
CVA2508F	161107009-088	0.003	11/23/2016 21:42	2508	Sink	P		
CVA2508G	161107009-089	0.002	11/23/2016 21:59	2508	Sink	P		
CVA2508H	161107009-090	0.002	11/23/2016 22:16	2508	Sink	P		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA2508I	161107009-091	0.004	11/23/2016 22:22	2508	Sink	P		
CVA2508J	161107009-092	0.192	11/23/2016 22:36	2508	Sink	P	Handles Removed	
CVA2508K	161107009-093	0.001	11/23/2016 22:42	2508	Sink	P		
CVA2508L	161107009-094	0.042	11/23/2016 22:56	2508	Sink	P	Handles Removed	
CVA2508M	161107009-095	0.007	11/23/2016 23:02	2508	Sink	P		
CVA2508N	161107009-096	0.015	11/23/2016 23:19	2508	Sink	P		
CVA2509	161107009-074	0.176	11/25/2016 14:53	2509	Sink	P	Handles Removed	
CVA2509A	161107009-073	0.117	11/23/2016 14:07	2509 A	Sink	P	Handles Removed	
CVA2511A	161107009-061	0.001	11/22/2016 21:44	2511	Sink	P		
CVA2511B	161107009-062	0.016	11/22/2016 21:50	2511	Sink	P	Handles Removed	
CVA2511C	161107009-063	0.003	11/22/2016 21:55	2511	Sink	P		
CVA2511D	161107009-064	0.002	11/22/2016 22:01	2511	Sink	P		
CVA2511E	161107009-065	0.003	11/22/2016 22:07	2511	Sink	P		
CVA2511F	161107009-066	0.384	11/22/2016 22:46	2511	Sink	P	Handles Removed	
CVA2511G	161107009-067	0.003	11/22/2016 23:02	2511	Sink	P		
CVA2511H	161107009-068	0.008	11/23/2016 11:04	2511	Sink	P		
CVA2511I	161107009-069	< 0.001	11/23/2016 11:20:53AM	2511	Sink	P		
CVA2511J	161107009-070	0.004	11/23/2016 11:37:12SM	2511	Sink	P		
CVA2511K	161107009-071	0.712	11/23/2016 12:37	2511	Sink	P	Handles Removed	

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVA2511L	161107009-072	0.289	11/23/2016 12:40	2511	Sink	P	Handles Removed	
CVA2513S	161107009-058	0.005	11/22/2016 21:16	2513	Slop Sink	P		
CVAF10	161107007-133	0.001	11/17/2016 16:05	2430	Drinking Fountain	Y		
CVAF11	161107007-137	< 0.001	11/17/2016 16:28	2429	Drinking Fountain	Y		
CVAF12A	161107009-059	< 0.001	11/22/2016 21:22	2513	Drinking Fountain	y		
CVAF12B	161107009-060	< 0.001	11/22/2016 21:39	2513	Drinking Fountain	y		
CVAF13A	161107007-114	< 0.001	11/17/2016 12:55	509	Drinking Fountain	Y		
CVAF13B	161107007-115	< 0.001	11/17/2016 13:06	509	Drinking Fountain	Y		
CVAF1A	161107007-057	< 0.001	11/16/2016 13:36	1303	Drinking Fountain	Y		
CVAF1B	161107007-058	< 0.001	11/16/2016 13:53	1303	Bottle Filler	Y		
CVAF2	161107007-069	< 0.001	11/16/2016 15:07	1216	Drinking Fountain	Y		
CVAF3A	161107007-045	< 0.001	11/16/2016 11:20	1104Hallway	High Drinking Fountain	Y		
CVAF3B	161107007-046	< 0.001	11/16/2016 11:26	1104Hallway	Low Drinking Fountain	Y		
CVAF4	161107007-048	< 0.001	11/16/2016 11:38:33AM	1109 Hallway	Left Drinking Fountain	Y		
CVAF4A	161107007-049	< 0.001	11/16/2016 12:06	1109 Hallway	Bottle Filler	Y		
CVAF4R	161107007-047	< 0.001	11/16/2016 11:32:53AM	1109 Hallway	Right Drinking Fountain	Y		
CVAF5A	161107009-043	< 0.001	11/22/2016 18:59	1123 Hallway	High Drinking Fountain	Y		
CVAF5B	161107009-044	< 0.001	11/22/2016 19:05	1123 Hallway	Low Drinking Fountain	Y		
CVAF6	161107007-026	< 0.001	11/10/2016 17:53	1429 Hallway	Drinking Fountain	Y		

Central Valley Academy Lead Testing Results

Sample ID	Test Number	Lead PPM	Sample Date/Time	Location (Room#, Hallway, etc.)	Outlet Type (Sink/Fountain, etc.)	Used for Drinking/Cooking	Notes	Remediation
CVAF7A	161107007-006	< 0.001	11/10/2016 14:58	1509 Indoor Track	High Drinking Fountain	Y		
CVAF7B	161107007-007	< 0.001	11/10/2016 15:32	1509 Indoor Track	Low Drinking Fountain	Y		
CVAF8	161107009-055	0.002	11/22/2016 20:58	1421Hallway	Drinking Fountain	Y		
CVAF9	161107009-037	< 0.001	11/22/2016 18:05	1440 Hallway	Drinking Fountain	Y		
CVAS1	161107007-125	< 0.001	11/17/2016 15:04	Concession Inside	Sink	Y		
CVAS2	161107007-126	< 0.001	11/17/2016 15:09	Concession Outside	Sink	Y		
CVAS3A	161107009-125	0.001	11/24/2016 4:35:24AM	Outside Men	Sink	P		
CVAS3B	161107009-126	0.002	11/24/2016 4:40:52SM	Outside Men	Sink	P		
CVAS4A	161107009-127	0.003	11/24/2016 4:46	Outside Women	Sink	P		
CVAS4B	161107009-128	0.006	11/24/2016 4:51	Outside Women	Sink	P		